



Maintenance Capability List

Revision: **157**

Date: **January 20, 2025**

Chapter - Page: 0 – 1 / 13

Hamilton Sundstrand Poland Maintenance Organization

Maintenance Capability List

Certificate Number: FAA 2HSY240B; EASA PL.145.007, TCCA 812-04

Revision: **157**

W zastępstwie:

Revision Date: **January 20, 2025**

Approved By: _____

Kierownik Systemu Jakości

Repair Quality Manager

Address: Hamilton Sundstrand Poland Sp. z o. o.

Hetmańska Street 120
35-078 Rzeszów
Poland

COPYRIGHT © HAMILTON SUNDSTRAND POLAND SP. Z O.O.. THIS DOCUMENT IS THE PROPERTY OF HAMILTON SUNDSTRAND POLAND SP. Z O.O. (HSP). YOU MAY NOT POSSESS, USE, COPY OR DISCLOSE THIS DOCUMENT OR ANY INFORMATION IN IT, FOR ANY PURPOSE, INCLUDING WITHOUT LIMITATION, TO DESIGN, MANUFACTURE OR REPAIR PARTS, OR OBTAIN ANY GOVERNMENT APPROVAL TO DO SO, WITHOUT HSP'S EXPRESS WRITTEN PERMISSION. NEITHER RECEIPT NOR POSSESSION OF THIS DOCUMENT ALONE, FROM ANY SOURCE, CONSTITUTES SUCH PERMISSION. POSSESSION, USE, COPYING OR DISCLOSURE BY ANYONE WITHOUT HSP'S EXPRESS WRITTEN PERMISSION IS NOT AUTHORIZED AND MAY RESULT IN CRIMINAL AND/OR CIVIL LIABILITY.
ECCN 9E999 (REVIEWED NOT SUBJECT TO EXPORT CONTROL)



Maintenance Capability List

Revision: **157**

Date: **January 20, 2025**

Chapter - Page: 0 – 2 / 13

PROCEDURE FOR IMPLEMENTATION OF CHANGES

1. Each change in Maintenance Capability List is marked in blue in the change made in the text.
2. The document is updated and distributed by Quality Repair Department's employee.
3. Details procedure regarding performing changes to Capability List is described in MOE **1.10 and 1.11**
4. Maintenance Capability List together with self-evaluation/ WF Extend CL-similar PN/Repair are kept in Repair Quality Department.
5. All editions of this document are subject to archiving in accordance with the MOE.



Maintenance Capability List

Revision: 125

Date: December 09, 2022

Chapter - Page: 0 – 3 / 13

TABLE OF CONTENTS

PROCEDURE FOR IMPLEMENTATION OF CHANGES	0-2/13
TABLE OF CONTENTS.....	0-3/13
RECORD OF REVISION.....	0-4/13
LIST OF EFFECTIVE PAGES.....	0-10/13
CHAPTER 1:	
APU MAKE AND MODELS.....	1-1/10
CHAPTER 2:	
2.1. APU PARTS NUMBER.....	2- 1/40
2.2 LRU PARTS NUMBER.....	2-29/40
CHAPTER 3:	
FAN DRIVE GEAR SYSTEM.....	3-1/2
3.1. FAN DRIVE GEAR SYSTEM COMPONENTS	3-2/2



Maintenance Capability List

Revision: 125

Date: December 09, 2022

Chapter - Page: 0 – 4 / 13

RECORD OF REVISION

Revision Number	Type of change (significant or insignificant)	Revision Date	Revised Pages
Original	Not applicable	December 2, 2011	ALL
1	Not applicable	December 22, 2011	9
2	Not applicable	June 06, 2012	ALL
3	Not applicable	August 08, 2012	2
	Not applicable		3
	Not applicable		10
	Not applicable		11
4	Not applicable	August 28, 2012	11
5	Not applicable	October 24, 2012	11
	Not applicable		12
6	Not applicable	November 16, 2012	11, 12, 13
7	Not applicable	November 30, 2012	13
8	Not applicable	December 14, 2012	11, 13
9	Not applicable	January 29, 2013	11, 12, 13, 14
10	Not applicable	February 22, 2013	13, 15
11	Not applicable	March 18, 2013	10, 11, 12, 13, 14, 15, 16
12	Not applicable	April 12, 2013	12, 13, 14
13	Not applicable	May 13, 2013	12, 14, 17
14	Not applicable	June 06, 2013	1, 2, 3, 4, 12, 13, 14, 15, 17, 18, 19
15	Not applicable	June 28, 2013	1, 3, 4, 16, 19
16	Not applicable	August 19, 2013	1, 3, 4, 15, 16, 17, 18
17	Not applicable	August 22, 2013	1, 3, 4, 15
18	Not applicable	September 23, 2013	1, 4, 5, 20
19	Not applicable	October 03, 2013	1, 4, 5, 10, 12, 16
20	Not applicable	November 13, 2013	1, 4, 5, 14, 16, 20
21	Not applicable	December 16, 2013	1, 4, 5, 17, 19, 21
22	Not applicable	January 13, 2014	1, 4, 5, 14, 15, 17
23	Not applicable	February 10, 2014	1, 4, 5, 13, 14, 17, 19, 21, 22
24	Not applicable	April 11, 2014	1, 2, 4, 5, 13, 14, 16, 17, 22



Maintenance Capability List

Revision: 125

Date: December 09, 2022

Chapter - Page: 0 – 5 / 13

Revision Number	Type of change (significant or insignificant)	Revision Date	Revised Pages
25	Not applicable	August 08, 2014	1, 3, 5, 6, 7, 16, 17, 18, 22, 23, 24
26	Not applicable	November 14, 2014	1, 3, 5, 6, 7, 15, 18, 19, 20, 21, 25
27	Not applicable	November 28, 2014	1, 5, 6, 7, 19, 20
28	Not applicable	February 11, 2015	1, 5, 6, 15, 18, 20
29	Not applicable	May 07, 2015	1, 3, 5, 6, 14, 20, 21
30	Not applicable	June 03, 2015	1, 5, 6, 17, 19, 21
31	Not applicable	August 06, 2015	1, 3, 5, 6, 7, 11, 12, 13, 14, 16, 17, 20, 21, 22, 24, 25, 26, 27, 28, 29, 30, 31
32	Not applicable	August 24, 2015	1, 5, 6, 7, 26, 29, 30
33	Not applicable	October 07, 2015	1, 3, 5, 6, 7, 22, 24, 25, 29, 30, 31, 32
34	Not applicable	December 17, 2015	1, 3, 5, 6, 7, 18, 19, 23, 24, 26, 30, 32, 34
35	Not applicable	March 01, 2016	1, 5, 6, 7, 17, 20, 23, 26, 27
36	Not applicable	April 22, 2016	1, 3, 5, 6, 7, 26, 27, 31, 35
37	Not applicable	May 13, 2016	1, 5, 6, 7, 33, 35
38	Not applicable	June 09, 2016	1, 3, 5, 6, 7, 21, 27, 31, 33, 36
39	Not applicable	October 26, 2016	1, 3, 6, 7, 8, 18, 26, 27, 28, 37
40	Not applicable	December 22, 2016	1, 3, 6, 7, 8, 25, 28, 29, 37, 38
41	Not applicable	March 15, 2017	1, 6, 7, 8, 29, 38
42	Not applicable	June 08, 2017	1, 3, 6, 7, 8, 12, 14, 15, 16, 18, 19, 20, 21, 23, 24, 25, 26, 27, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 40
43	Not applicable	October 20, 2017	1, 3, 6, 7, 8, 29, 30, 37, 39
44	Not applicable	January 12, 2018	1, 3, 6, 7, 8, 21, 32, 37, 39, 40, 41
45	Not applicable	March 19, 2018	0-1/8, 0-3/8, 0-6/8, 0-7/8, 0-8/8, 1-1/8, 2-1/26, 2-3/26, 2-8/26, 2-17/26, 2-26/26, 3-1/1



Maintenance Capability List

Revision: 125

Date: December 09, 2022

Chapter - Page: 0 – 6 /13

Revision Number	Type of change (significant or insignificant)	Revision Date	Revised Pages
46	Not applicable	May 30, 2018	0-1/8, 0-3/8, 0-6/8, 0-7/8, 0-8/8, 1-4/8, 1-7-8, 2-1/28, 2-2/28, 2-3/28, 2-4/28, 2-5/28, 2-6/28, 2-7/28, 2-8/28, 2-9/28, 2-10/28, 2-11/28, 2-12/28, 2-13/28, 2-14/28, 2-15/28, 2-16/28, 2-17/28, 2-18/28, 2-19/28, 2-20/28, 2-21/28, 2-22/28, 2-23/28, 2-24/28, 2-25/28, 2-26/28, 2-27/28, 2-28/28
47	Not applicable	August 20, 2018	0-1/8, 0-6/8, 0-7/8, 0-8/8, 2-17/28, 2-23/28, 2-25/28
48	Not applicable	October 12, 2018	0-1/8, 0-6/8, 0-7/8, 0-8/8, 2-5/29, 2-8/29, 2-14/29, 2-16/29, 2-17/29, 2-28/29
49	Not applicable	December 18, 2018	0-1/8, 0-3/8, 0-6/8, 0-7/8, 0-8/8, Chapter 2 – all pages
50	Not applicable	January 28, 2019	Chapter 0 – all pages, Chapter 2 – all pages
51	Not applicable	February 11, 2019	0-1/9, 0-6/9, 0-7/9, 0-8/9, 2-3/31, 2-20/31
52	Not applicable	February 15, 2019	0-1/9, 0-6/9, 0-7/9, 0-8/9, 2-4/31, 2-18/31
53	Not applicable	March 5, 2019	Chapter 0 – all pages, 2-9/31
54	Not applicable	March 11, 2019	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2-25/31, 2-9/31
55	Not applicable	March 12, 2019	0-1/10, 2 – 21 / 31
56	Not applicable	April 03, 2019	0-1/10, 0-7/10, 0-8/10, 0-9/10, 0-10/10, 2-4/31, 2-9/31, 2-25/31, 2-30/31
57	Not applicable	April 26, 2019	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2–3/31, 2–21/31
58	Not applicable	May 14, 2019	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2-3/31, 2-21/31, 2-24/31
59	Not applicable	June 26, 2019	0-1/10, 0-7/10, 0-8/10, 0-9/10, 0-10/10, 2-21/31, 2-24/31, 3-1/1
60	Not applicable	July 12, 2019	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2-7/31, 2-23/31
61	Not applicable	October 23, 2019	0-1/10, 0-7/10, 0-8/10, 0-9/10, 0-10/10, chapter 2- all pages
62	Not applicable	November 25 , 2019	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2-21/32
63	Not applicable	December 10, 2019	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2-21/32



Maintenance Capability List

Revision: 125

Date: December 09, 2022

Chapter - Page: 0 – 7 / 13

Revision Number	Type of change (significant or insignificant)	Revision Date	Revised Pages
64	Not applicable	December 16, 2019	0-1/10, 0-7/10, 0-8/10, 0-10/10, 2-32/32
65	Not applicable	January 16, 2020	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2-25/32
66	Not applicable	January 17, 2020	0-1/10,0-3/10, 0-7/10, 0-8/10, 0-10/10, 3-1/2, 3-2/2
67	Not applicable	January 27, 2020	0-1/10, 0-7/10, 0-8/10, 0-9/10, 0-10/10, chapter 2- all pages
68	Not applicable	February 05, 2020	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2-17/33
69	Not applicable	February 13, 2020	0-1/10, 0-7/10, 0-8/10, 0-9/10, 0-10/10, 2-26/33, 2-32/33
70	Not applicable	February 17, 2020	0-1/10, 0-2/10, 0-7/10, 0-8/10, 0-9/10, 2-1/33, 2-9/33
71	Not applicable	March 02, 2020	0-1/10, 0-7/10, 0-8/10, 0-9/10, 0-10/10, 2-22/33, 2-25/33, 2-27/33, 2-32/33
72	Not applicable	March 12, 2020	0-1/10, 0-7/10, 0-8/10, 0-10/10, 3-2/2
73	Not applicable	May 11, 2020	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2-9/33, 2-22 /33
74	Not applicable	May 25, 2020	0-1/10, 0-7/10, 0-8/10, 0-9/10, 0-10/10, 2-9/33, 2-10/33, 2-11/33, 2-18/33, 2-32/33
75	Not applicable	July 22, 2020	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2-14/33
76	Not applicable	September 03, 2020	0-1/10, 0-7/10, 0-8/10, 0-9/10, 2-16/33, 2-18/33
77	Not applicable	September 24, 2020	Chapter 1 – all pages, chapter 2 – all pages
78	Not applicable	December 09, 2020	0-1/10, 0-8/10, 0-9/10, 0-10/10, 2-23/35, 2-22/35
79	Not applicable	December 18, 2020	0-1/11, 0-8/11, 0-9/11, 0-10/11, 2-9/35, 2-23/35, 2-24/35
80	Not applicable	January 21, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 2-24/35
81	Not applicable	January 22, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 2-24/35
82	Not applicable	February 10, 2021	0-1/11, 0-8/11, 0-9/11, 0-11/11, 3-1/2
83	Not applicable	March 02, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 2-24/35
84	Not applicable	March 23, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 0-11/11, 1-8/8, 2-24/35, 2-34/35
85	Not applicable	March 25, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 0-11/11, Chapter 1 – all pages, Chapter 2 – all pages
86	Not applicable	May 07, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 2-24 / 36
87	Not applicable	May 26, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 2-20 / 36
88	Not applicable	June 01, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 2-19 / 36
89	Not applicable	June 29, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 0-11/11, Chapter 2 – all pages



Maintenance Capability List

Revision: 125

Date: December 09, 2022

Chapter - Page: 0 – 8 / 13

Revision Number	Type of change (significant or insignificant)	Revision Date	Revised Pages
90	Not applicable	July 01, 2021	0-1/11, 0-8/11, 0-9/11, 0-11/11, 2-30/38
91	Not applicable	July 05, 2021	0-1/11, 0-8/11, 0-9/11, 0-11/11, 2-30/38
92	Not applicable	July 12, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 2-25/38
93	Not applicable	July 13, 2021	0-1/11, 0-8/11, 0-9/11, 0-11/11, 2-37/38
94	Not applicable	Sep 08, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 0-11/11, 2 – 22 / 38
95	Not applicable	Sep 29, 2021	0-1/11, 0-8/11, 0-9/11, 0-11/11, 3-1/2
96	Not applicable	Oct 19, 2021	0-1/11, 0-8/11, 0-9/11, 0-8/11, 2–30/38
97	Not applicable	Nov 25, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 2-25/38
98	Not applicable	Dec 07, 2021	0-1/11, 0-8/11, 0-9/11, 0-11/11, 2-37/38, 3-1/2, 3-2/2
99	Not applicable	Dec 22, 2021	0-1/11, 0-8/11, 0-9/11, 0-10/11, 0-11/11, 2-25 / 38, 2-37/ 38,
100	Not applicable	Jan 12, 2022	0-1/11, 0-8/11, 0-9/11, 3-1/2, 3-2/2
101	Not applicable	Jan 24, 2022	0-1/11, 0-2/11, 0-8/11, 0-9/11, 0-11/11, 2-37/38,
102	Not applicable	Jan 28, 2022	Chapter 0 – all pages, 3-2/2
103	Not applicable	Feb 02, 2022	0-1/12, 0-9/12, 0-10/12, 0-12/12, 2-31/38, 2-32/38, 2-33/38, 2-36/38
104	Not applicable	Feb 10, 2022	0-1/12, 0-3/12, 0-9/12, 0-10/12, 0-11/12, 0-12/12, Chapter 2 – all pages
105	Not applicable	Feb 15, 2022	0-1/12, 0-9/12, 0-10/12, 0-11/12, 0-12/12, 2-27/40, 2-28/40, 2-35/40, 2-40/40
106	Not applicable	Mar 03, 2022	0-1/12, 0-9/12, 0-10/12, 0-11/12, 0-12/12, 2-17/40, 2-28/40, 2-31/40, 2-34/40
107	Not applicable	Mar 11, 2022	0-1/12, , 0-9/12, 0-10/12, 0-12/12, 2-39/40
108	Not applicable	Mar 24, 2022	0-1/12, 0-9/12, 0-10/12, 0-11/12, 0-12/12, 1-1/10, 1-2/10, 1-3/10, 1-4/10, 1-5/10, 1-6/10, 1-7/10, 1-8/10, Chapter 2 – all pages, Chapter 3- all pages
109	Not applicable	Apr 09, 2022	0-1/12, 0-9/12, 0-10/12, 0-11/12, 2-8/40
110	Not applicable	Apr 14, 2022	0-1/12, 0-9/12, 0-10/12, 1-9/10
111	Not applicable	Apr 20, 2022	0-1/12, 0–8/12, 0-10/12, 1-9/10
112	Not applicable	Apr 26, 2022	0-1/12, 0–8/12, ,0-10/12, ,0-11/12, 2-28-40
113	Not applicable	May 09, 2022	0-1/12, 0–8/12, 0-10/12, 0-11/12, 2-28-40



Maintenance Capability List

Revision: 125

Date: December 09, 2022

Chapter - Page: 0 – 9 / 13

Revision Number	Type of change (significant or insignificant)	Revision Date	Revised Pages
114	Not applicable	May 25, 2022	0-1/12, 0-9/12, 0-10/12, 0-11/12, 2-28-40
115	Not applicable	June 06, 2022	0-1/12, 0-9/12, 0-10/12, 0-12/12, 2-40-40
116	Not applicable	June 27, 2022	0-1/12, 0-9/12, 0-10/12, 0-11/12, 2-28-40
117	Not applicable	July 14, 2022	0-1/12, 0-9/12, 0-10/12, 0-12/12, 3-1/2
118	Not applicable	August 12, 2022	0-1/12, 0-9/12, 0-10/12, 0-11/12, 2-17/40
119	Not applicable	August 22, 2022	0-1/12, 0-9/12, 0-10/12, 0-11/12, 2-28/40
120	Not applicable	September 05, 2022	0-1/12, 0-9/12, 0-10/12, 0-11/12, 2-16/40
121	Not applicable	September 14, 2022	0-1/12, 0-9/12, 0-10/12, 0-12/12, 3-1/2
122	Not applicable	October 05, 2022	Chapter 0 – all pages, 2-5/40, 2-21/40
123	Not applicable	November 02, 2022	0-1/13, 0-10/13, 0-11/13, 0-12/13, 2-28/40
124	Not applicable	November 25, 2022	0-1/13, 0-10/13, 0-11/13, 0-13/13, 2-5/40, 2-35/40
125	insignificant	December 09, 2022	0-1/12, 0-2/13, 0-3/13, 0-4/13, 0-5/13, 0-6/13, 0-7/13, 0-8/13, 0-9/13, 0-10/13, 0-11/13
126	insignificant	February 28, 2023	0-1/13, 0-10/13, 0-11/13, 0-13/13, 2-33/40
127	insignificant	March 15, 2023	0-1/13, 0-10/13, 0-11/13, 0-12/13, 0-13/13, 2-21/40, 2-24/40, 2-35/40, 2-40/40
128	insignificant	April 04, 2023	0-1/13, 0-10/13, 0-11/13, 2-40/40
129	insignificant	April 26, 2023	0-1/13, 0-10/13, 0-11/13, 2-5/40
130	insignificant	June 07, 2023	0-1/13, 0-10/13, 0-11/13, 0-12/13, 2-7/40
131	insignificant	July 28, 2023	0-1/13, 0-10/13, 0-11/13, 0-13/13, 2-30/40
132	insignificant	August 09, 2023	0-1/13, 0-10/13, 0-11/13, 0-12/13, 0-13/13, 2-22/40, 2-32/40
133	insignificant	August 16, 2023	0-1/13, 0-10/13, 0-11/13, 0-12/13, 2-21/40
134	insignificant	September 05, 2023	0-1/13, 0-10/13, 0-11/13, 0-13/13, 2-33/40, 2-35/40
135	insignificant	September 14, 2023	0-1/13, 0-10/13, 0-11/13, 2-3/40, 2-4/40
136	insignificant	September 26, 2023	0-1/13, 0-10/13, 0-11/13, 0-9/13, 2-28/40
137	insignificant	November 07, 2023	0-1/13, 0-10/13, 0-11/13, 0-13/13, 2-34/40, 2-38/40



Revision: **157**
 Date: **January 20, 2025**
 Chapter - Page: 0 – 10 / 13

Maintenance Capability List

Revision Number	Type of change (significant or insignificant)	Revision Date	Revised Pages
138	insignificant	January 03, 2024	0-1/13, 0-10/13, 0-11/13, 0-12/13, 2-19-40
139	insignificant	January 11, 2024	0-1/13, 0-10/13,
140	insignificant	January 11, 2024	0-1/13, 0-10/13, 0-12/13, 2-26/40, 2-40/40
141	insignificant	January 24, 2024	0-1/13, 0-10/13, 0-11/13, 0-12/13, 0-13/13, 2-25/ 40, 2-40 /40
142	insignificant	January 26, 2024	0-1/13, 0-10/13, 0-11/13, 0-13/13, 2-40 /40
143	insignificant	February 29, 2024	0-1/13, 0-10/13, 0-11/13, 0-12/13, 0-13/13, Chapter 2 – all pages
144	insignificant	March 18, 2024	0-1/13, 0-10/13, 0-11/13, 0-13/13, 2–36/43, 2–38/43
145	insignificant	April 11, 2024	0-1/13, 0-10/13, 0-11/13, 0-13/13, 1-8/10, 2–37/43
146	insignificant	June 03, 2024	0-1/13, 0-10/13, 0-11/13, 0-12/13, 2-7/43, 2-20/43, 2-28/43
147	insignificant	June 18, 2024	0-1/13, 0-10/13, 0-11/13, 0-12/13, 0-13/13, 2-28/43, 2-41/43
148	insignificant	June 24, 2024	0-1/13, 0-10/13, 0-11/13, 0-13/13, 2-41/43
149	insignificant	June 28, 2024	0-1/13, 0-10/13, 0-11/13, 0-12/13, 2–17 /43
150	insignificant	July 05, 2024	0-1/13, 0-10/13, 0-11/13, 0-13/13 3-1/3, 3-2/3, 3-3/3
151	insignificant	August 08, 2024	0-1/13, 0-10/13, 0-11/13, 0-13/13, 1-9/10, 2-31/43, 3-2/3,
152	insignificant	August 13, 2024	0-1/13, 0-10/13, 0-11/13, 2-3/43
153	insignificant	October 21, 2024	0-1/13, 0-10/13, 0-11/13, 2-2/43
154	insignificant	November 18, 2024	0-1/13, 0-10/13, 0-11/13, 0-12/13, 0-13/13, 2-7/43, 2-27/43, 2-33/43, 2-34/43
155	insignificant	December 09, 2024	0-1/13, 0-10/13, 0-11/13, 0-12/13, 2-10/43, 2-27/43
156	insignificant	December 19, 2024	0-1/13, 0-10/13, 0-11/13, 0-12/13, 0-13/13, 2-37/43
157	significant	January 20, 2025	0-1/13, 0-2/13, 0-10/13, 0-11/13, 0-13/13, 1-1/10, 1-2/10, 1-3/10, 1-4/10, 1-5/10, 1-6/10, 1-7/10, 1-8/10, 1-9/10, 4-1/1



Maintenance Capability List

Revision: **157**

Date: **January 20, 2025**

Chapter - Page: 0 – 11 / 13

LIST OF EFFECTIVE PAGES

Section	Page No.	Revision	Date
CHAPTER 0: COVER PAGE PROCEDURE FOR IMPLEMENTATION OF CHANGES TABLE OF CONTENTS RECORD OF REVISION LIST OF EFFECTIVE PAGES	0-1/13	157	January 20, 2025
	0-2/13	157	January 20, 2025
	0-3/13	125	December 09, 2022
	0-4/13	125	December 09, 2022
	0-5/13	125	December 09, 2022
	0-6/13	125	December 09, 2022
	0-7/13	125	December 09, 2022
	0-8/13	125	December 09, 2022
	0-9/13	125	December 09, 2022
	0-10/13	157	January 20, 2025
	0-11/13	157	January 20, 2025
	0-12/13	156	December 19, 2024
	0-13/13	157	January 20, 2025
CHAPTER 1: APU MAKE AND MODELS	1-1/10	157	January 20, 2025
	1-2/10	157	January 20, 2025
	1-3/10	157	January 20, 2025
	1-4/10	157	January 20, 2025
	1-5/10	157	January 20, 2025
	1-6/10	157	January 20, 2025
	1-7/10	157	January 20, 2025
	1-8/10	157	January 20, 2025
	1-9/10	157	January 20, 2025
	1-10/10	85	March 25, 2021
CHAPTER 2: 2.1 APU PARTS NUMBERS	2-1/43	143	February 29, 2024
	2-2/43	153	October 21, 2024
	2-3/43	152	August 13, 2024
	2-4/43	143	February 29, 2024
	2-5/43	143	February 29, 2024



Maintenance Capability List

Revision: 156

Date: December 19, 2024

Chapter - Page: 0 – 12 / 13

Section	Page No.	Revision	Date
	2-6/43	156	December 19, 2024
	2-7/43	154	November 18, 2024
	2-8/43	143	February 29, 2024
	2-9/43	143	February 29, 2024
	2-10/43	155	December 09, 2024
	2-11/43	143	February 29, 2024
	2-12/43	143	February 29, 2024
	2-13/43	143	February 29, 2024
	2-14/43	143	February 29, 2024
	2-15/43	143	February 29, 2024
	2-16/43	143	February 29, 2024
	2-17/43	149	June 28, 2024
	2-18/43	156	December 19, 2024
	2-19/43	143	February 29, 2024
	2-20/43	146	June 03, 2024
	2-21/43	143	February 29, 2024
	2-22/43	143	February 29, 2024
	2-23/43	143	February 29, 2024
	2-24/43	143	February 29, 2024
	2-25/43	143	February 29, 2024
	2-26/43	143	February 29, 2024
	2-27/43	155	December 09, 2024
	2-28/43	147	June 18, 2024
	2-29/43	143	February 29, 2024



Maintenance Capability List

Revision: **157**

Date: **January 20, 2025**

Chapter - Page: 0 – 13 / 13

Section	Page No.	Revision	Date
	2-30/43	143	February 29, 2024
2.2 LRU PARTS NUMBERS	2-31/43	151	August 08, 2024
	2-32/43	143	February 29, 2024
	2-33/43	154	November 18, 2024
	2-34/43	154	November 18, 2024
	2-35/43	143	February 29, 2024
	2-36/43	144	March 18, 2024
	2-37/43	156	December 19, 2024
	2-38/43	144	March 18, 2024
	2-39/43	143	February 29, 2024
	2-40/43	143	February 29, 2024
	2-41/43	148	June 24, 2024
	2-42/43	143	February 29, 2024
	2-43/43	143	February 29, 2024
	CHAPTER 3: FAN DRIVE GEAR SYSTEM	3-1/3	150
3.1 FAN DRIVE GEAR SYSTEM COMPONENTS	3-2/3	151	August 08, 2024
	3-3/3	150	July 05, 2024
CHAPTER 4: PT6A MAKE AND MODELS	4-1/1	157	January 20, 2025



Maintenance Capability List

Revision: **157**

Date: **January 20, 2025**

Chapter - Page: 1 – 1 / 10

CHAPTER 1: APU MAKE AND MODELS

Aircraft	Workshop	Make (OEM Mfg)	Model	Part Number	Description	Approved or Accepted Data	ATA Code	EASA Rating	Capability Rating
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	4500001 series	Auxiliary Power Unit	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-00-00	B3	Inspection, Repair, Modifications, Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	70LM041030	Power Section Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications, Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	70LM041040	Power Section Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications, Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	70LM041070	Power Section Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications, Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	70LM041060	Power Section Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications, Test



Revision: 157

Date: January 20, 2025

Chapter - Page: 1 – 2 / 10

Maintenance Capability List

Aircraft	Workshop	Make (OEM Mfg)	Model	Part Number	Description	Approved or Accepted Data	ATA Code	EASA Rating	Capability Rating
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	70LM041100	Power Section Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications , Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	70LM041080	Power Section Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications , Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	70LM041090	Power Section Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications , Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	4503908 series 4520456 4520516	Power Section Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications , Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	M4503908 series	Power Section Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications , Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	70LM021000	Load Compressor Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-23-00	C7	Inspection, Repair, Modifications , Test



Revision: 157

Date: January 20, 2025

Chapter - Page: 1 – 3 / 10

Maintenance Capability List

Aircraft	Workshop	Make (OEM Mfg)	Model	Part Number	Description	Approved or Accepted Data	ATA Code	EASA Rating	Capability Rating
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	70LM021010	Load Compressor Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-23-00	C7	Inspection, Repair, Modifications , Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	70LM021020	Load Compressor Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-23-00	C7	Inspection, Repair, Modifications , Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	4504433 series 4520454 4520515	Load Compressor Module	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-23-00	C7	Inspection, Repair, Modifications , Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	756407 series 4520497 01R756407 Series	Gearbox	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-26-00	C7	Inspection, Repair, Modifications , Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	756408 series	Gearbox	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-26-00	C7	Inspection, Repair, Modifications , Test



Revision: 157

Date: January 20, 2025

Chapter - Page: 1 – 4 / 10

Maintenance Capability List

Aircraft	Workshop	Make (OEM Mfg)	Model	Part Number	Description	Approved or Accepted Data	ATA Code	EASA Rating	Capability Rating
Embraer ERJ 170, ERJ 190	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2300	4505000 series	Auxiliary Power Unit	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-00-00	B3	Inspection, Repair, Modifications, Test
Embraer ERJ 170, ERJ 190	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2300	4505001 series	Auxiliary Power Unit	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-00-00	B3	Inspection, Repair, Modifications, Test
Embraer E-Jet	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2600E	4509879 series 4954227 series 4508022 series 4510400 series 4509880 series	Auxiliary Power Unit	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instructions	49-00-00	B3	Inspection, Repair, Modifications, Test
Embraer ERJ 170, ERJ 190	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2300	4505011 series	Power head assembly	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-20-02	C7	Inspection, Repair, Modifications, Test
Embraer ERJ 170, ERJ 190 Comac ARJ21 MRJ-70 MRJ-90	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M	4505015 series	Gearbox assembly	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instruction	49-26-01	C7	Inspection, Repair, Modifications, Test



Maintenance Capability List

Revision: 157

Date: January 20, 2025

Chapter - Page: 1 – 5 / 10

Aircraft	Workshop	Make (OEM Mfg)	Model	Part Number	Description	Approved or Accepted Data	ATA Code	EASA Rating	Capability Rating
Boeing 787	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 5000	7002907H series	Auxiliary Power Unit	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-00-00	B3	Inspection, Repair, Modifications, Test
Boeing 787	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 5000	7000063 series	Power head assembly	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-20-02	C7	Inspection, Repair, Modifications, Test
Boeing 787	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 5000	7000064 series	Gearbox assembly	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-26-01	C7	Inspection, Repair, Modifications, Test
Boeing 787	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 5000	7000001H series	Auxiliary Power Unit	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-00-00	B3	Inspection, Repair, Modifications, Test
Comac ARJ21	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2600A	4506750 series	Auxiliary Power Unit	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-10-01	B3	Inspection, Repair, Modifications, Test



Maintenance Capability List

Revision: 157

Date: January 20, 2025

Chapter - Page: 1 – 6 / 10

Aircraft	Workshop	Make (OEM Mfg)	Model	Part Number	Description	Approved or Accepted Data	ATA Code	EASA Rating	Capability Rating
Comac ARJ21	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2600A	4507067 series	Power head assembly	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-20-02	C7	Inspection, Repair, Modifications, Test
AIRBUS A400-M	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240A	4507265 series	Auxiliary Power Unit	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-00-00	B3	Inspection, Repair, Modifications, Test
AIRBUS A400-M	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240A	4507368 series	Module Assembly, Power Section	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications, Test
AIRBUS A400-M EMBRAER KC-390	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240A APS 3240E	4507330 series	Module Assembly, Load Compressor	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instructions	49-23-00	C7	Inspection, Repair, Modifications, Test
AIRBUS A400-M EMBRAER KC-390	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240A APS 3240E	4507290 series	Gearbox Assembly	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instructions	49-26-00	C7	Inspection, Repair, Modifications, Test



Maintenance Capability List

Revision: 157

Date: January 20, 2025

Chapter - Page: 1 – 7 /10

Aircraft	Workshop	Make (OEM Mfg)	Model	Part Number	Description	Approved or Accepted Data	ATA Code	EASA Rating	Capability Rating
Embraer E-Jet	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2600E	4510108 series	Gearbox Assembly	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instructions	49-26-01	C7	Inspection, Repair, Modifications, Test
Embraer E-Jet	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2600E	4510300 series	Power Head Assembly	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instructions	49-20-02	C7	Inspection, Repair, Modifications, Test
EMBRAER MRJ-70 MRJ-90	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2600M	4508327 series	Auxiliary Power Unit	Engine Manual, Cleaning Inspection and Repair Manual, Customer Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instructions	49-00-00	B3	Inspection, Repair, Modifications, Test
EMBRAER MRJ-70 MRJ-90	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 2600M	4508460 series	Module Assembly, Power Section	Engine Manual, Cleaning Inspection and Repair Manual, Customer Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instruction	49-20-02	C7	Inspection, Repair, Modifications, Test



Maintenance Capability List

Revision: 157

Date: January 20, 2025

Chapter - Page: 1 – 8 / 10

Aircraft	Workshop	Make (OEM Mfg)	Model	Part Number	Description	Approved or Accepted Data	ATA Code	EASA Rating	Capability Rating
EMBRAER KC-390	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240E	4509594 series	Auxiliary Power Unit	Engine Manual, Cleaning Inspection and Repair Manual, Customer Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instructions	49-00-00	B3	Inspection, Repair, Modifications, Test
EMBRAER KC-390	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240E	4509730 series	Module Assembly, Power Section	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instructions	49-21-00	C7	Inspection, Repair, Modifications, Test
AIRBUS A400-M	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240A	4520535; 4520536; 4520397; 01R4520397; 4520471; 4520472;	LOAD COMPRESSOR MODULE ASSEMBLY	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual, Action Items and Information Letters, Repair Station Instructions	49-23-00	C7	Inspection, Repair, Modifications, Test
AIRBUS A400-M	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240A	4520383; 4520429; 4520473;	POWER SECTION MODULE ASSEMBLY	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications, Test
EMBRAER KC-390	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240E	4520383; 4520429; 4520566;	POWER SECTION MODULE ASSEMBLY	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications, Test



Maintenance Capability List

Revision: 157

Date: January 20, 2025

Chapter - Page: 1 – 9 / 10

Aircraft	Workshop	Make (OEM Mfg)	Model	Part Number	Description	Approved or Accepted Data	ATA Code	EASA Rating	Capability Rating
EMBRAER KC-390	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240E	4511079; 4520489; 4511079A;	LOAD COMPRESSOR MODULE ASSEMBLY	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-21-00	C7	Inspection, Repair, Modifications, Test
AIRBUS A400-M	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3240A	4520458;	Gearbox Assembly	Engine Manual, Cleaning Inspection and Repair Manual, Airlines Manuals, Components Maintenance Manual, Service Bulletins, Standard Practice Manual,	49-26-00	C7	Inspection, Repair, Modifications, Test
Airbus A318/ A319/ A320/A321	Hamilton Sundstrand Poland	Hamilton Sundstrand Poland	APS 3200	4520568, 4520604	Gearbox assembly	Engine Manual, Service Bulletins, SCTP A-780	49-26-00	C7	Inspection, Repair, Modifications, Test



Maintenance Capability List

Revision: 85

Date: March 25, 2022

Chapter - Page: 1 – 10 / 10

Place intentionally left blank.



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 1 / 43

CHAPTER 2:

2.1 APU PART NUMBERS

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	0332407160, M45054754, 4505475, 4503907 series, 0332407180, 0332407260, 0332407150	49-21-00-350-801, REPAIR-01 49-21-00-350-803, REPAIR-03	Disk assembly, turbine - first stage	C7
Hamilton Sundstrand Poland	APS 3200	4505477 series	49-21-00-350-804, REPAIR-04 49-21-00-350-806, REPAIR-06	Disk assembly, turbine - second stage	C7
Hamilton Sundstrand Poland	APS 5000	7007092B	49-24-03-340-801, REPAIR 08	2nd Stage Turbine Nozzle	C7
Hamilton Sundstrand Poland	APS 3240	4508587 4508956	49-21-00-350-810, REPAIR 25 49-21-00-350-811, REPAIR 26 49-21-00-320-803, REPAIR 27 49-21-00-040-805, Disassembly 05	First Stage Turbine Wheel	C7
Hamilton Sundstrand Poland	APS 3240A	4508476A 4508476B	49-21-00-350-818, REPAIR 44 49-21-00-350-819, REPAIR 45 49-21-00-040-806, Disassembly 06	Second Stage Turbine Wheel	C7
Hamilton Sundstrand Poland	APS 2300	4520542, 4520420, 4507866, 4505025 series	49-23-02-350-802, REPAIR 02	Wheel assembly, turbine, first stage	C7



Maintenance Capability List

Revision: 153

Date: October 21, 2024

Chapter - Page: 2 – 2 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M	4505025 series, 4507866, 4520542	49-23-02-350-802, REPAIR 02	Wheel assembly, turbine, first stage	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M	4505036 series, 4507867	49-23-02-350-803, REPAIR 03	Wheel assembly, turbine, second stage	C7
Hamilton Sundstrand Poland	APS 3200	0332407250, 0332407210, 0332407270	49-21-00-350-804, REPAIR 04 49-21-00-350-806, REPAIR 06	Wheel Second Stage	C7
Hamilton Sundstrand Poland	APS 5000	7002998, 7004291 7004291A 7006887, 7900044B, 7007072, 7900013	49-23-02-350-802, REPAIR 02	Turbine Wheel assembly, first stage	C7
Hamilton Sundstrand Poland	APS 5000	7002999, 7004381 7004381A 7006888, 7007073, 7900014, 7900045A	49-23-02-350-803, REPAIR 03	Turbine Wheel assembly, second stage	C7
Hamilton Sundstrand Poland	APS 5000	7003001, 7004382, 7006577, 7006778, 7007054, 7900043	TASK 49-23-02-350-806, Repair 13 TASK 49-23-02-350-807, Repair 14	DISK, TURBINE, 2ND STAGE, MACHINING	C7



Maintenance Capability List

Revision: 152

Date: August 13, 2024

Chapter - Page: 2 – 3 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	01RM4505475	49-21-00-040-807, Disassembly 06 49-21-00-350-801, REPAIR 01 49-21-00-350-803, REPAIR 03	1st Stage Turbine Wheel	C7
Hamilton Sundstrand Poland	APS 2300	4505036 series 4507867 4520422	49-23-02-350-803, REPAIR 03	Wheel assembly, turbine, second stage	C7
Hamilton Sundstrand Poland	APS 3240E	4508956	49-21-00-350-810, Repair 25 49-21-00-350-811, Repair 26 49-21-00-320-803, Repair 27 49-21-00-040-805, Disassembly 05	First Stage Turbine Wheel	C7
Hamilton Sundstrand Poland	APS 3240E	4508476B	49-21-00-350-818, Repair 44 49-21-00-350-819, Repair 45 49-21-00-040-806, Disassembly 06	Second Stage Turbine Wheel	C7
Hamilton Sundstrand Poland	APS 3200	4950811	49-21-10-350-802, REPAIR 03	Manifold Assy, Fuel-main	C7
Hamilton Sundstrand Poland	APS 3200	02RM4505475, 4520563, 01R4503907	49-21-00-040-807, Disassembly 06 49-21-00-350-801, REPAIR 01 49-21-00-350-803, REPAIR 03 RDTI 3200492100-TI-231026.1 rev.00	1st stage turbine disk	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 4 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2600E	4520012, 4520420	49-23-02-350-802, REPAIR 02	DISK ASSEMBLY, TURBINE, FIRST- STAGE	C7
Hamilton Sundstrand Poland	APS 2600E	4520013, 4520422	All Inspection according to 4511183CIR	DISK ASSEMBLY, TURBINE, SECOND- STAGE	C7
Hamilton Sundstrand Poland	APS 2600E	4520012, 4520420	All Inspection according to 4511183CIR	DISK ASSEMBLY, TURBINE, FIRST- STAGE	C7
Hamilton Sundstrand Poland	APS 5000	ALL	ALL INSPECTION ACCORDING TO CIR 4510763 SPM HSPS 490001	All P/N parts under inspection tasks	C7
Hamilton Sundstrand Poland	APS 2300	ALL	ALL INSPECTION ACCORDING TO 4511183 APS2300 CIR SPM HSPS 490001	All P/N parts under inspection tasks	C7
Hamilton Sundstrand Poland	APS 3200	ALL	All Inspection according to 4510733CIR SPM HSPS 490001	All P/N parts under inspection tasks	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Page: Page: 2 – 5 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2300	4506255, 4506255A, 4509329	49-23-02-350-823, REPAIR 08	Impeller	C7
Hamilton Sundstrand Poland	APS 5000	7001795 7003596	49-23-02-380-801, REPAIR 05 RDTI	Impeller	C7
Hamilton Sundstrand Poland	APS 5000	7004743B, 7004744	49-22-02-390-802, REPAIR 01 49-22-02-350-801, REPAIR 02 49-22-02-360-801, REPAIR 03 49-22-02-360-802, REPAIR 04 49-22-02-350-802, REPAIR 05 49-22-02-350-803, REPAIR 06 49-22-02-350-806, REPAIR 09 49-22-02-350-805, REPAIR 08	Air Inlet Plenum	C7
Hamilton Sundstrand Poland	APS 2600E	4520013 series, 4520422	49-23-02-350-803, REPAIR 03	Wheel assembly, turbine second stage	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600M	4505168 series	49-26-02-310-801, REPAIR 02 49-26-02-380-801, REPAIR 03 49-26-02-350-802, REPAIR 05	Gearbox Housing	C7



Maintenance Capability List

Revision: 156

Date: December 19, 2024

Page: Page: 2 – 6 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M	4951707	49-31-04-350-801, REPAIR 01	Primary Fuel Manifold	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M	4951708 4953150	49-31-05-350-801, REPAIR 01	Secondary Fuel Manifold	C7
Hamilton Sundstrand Poland	APS 3200	4505552 0332227310	49-23-10-360-802, REPAIR 02 49-23-10-350-802, REPAIR 08 49-23-10-380-802, REPAIR 14	Bearing Support Assy	C7
Hamilton Sundstrand Poland	APS 3200	756671	49-26-00-320-806, REPAIR 10	Bearing Support Assy	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600M	4951881, 4508603, 4508603A	49-22-02-390-801, REPAIR 01 49-22-02-360-801, REPAIR 03 49-22-02-360-802, REPAIR 04 49-22-02-360-803, REPAIR 05 49-22-02-350-801, REPAIR 06 49-22-02-350-802, REPAIR 07 49-22-02-350-803, REPAIR 08 49-22-02-350-804, REPAIR 09 49-22-02-350-805, REPAIR 10 49-22-02-350-810, REPAIR 15	Air Inlet Plenum	C7
Hamilton Sundstrand Poland	APS 3240A	0332220810 4504274	49-23-10-350-801, REPAIR 01	Gear Ring	C7
Hamilton Sundstrand Poland	APS 3240A APS 3240E	4507303	49-26-00-030-801 Disassembly 03 49-26-00-430-001 Assembly 01 49-26-00-430-001 Assembly 02	Pump Assembly Oil	C7



Revision: 146

Date: June 03, 2024

Page: Page: 2 – 7 / 43

Maintenance Capability List

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	0332228070, 4508034, 4508310, 0332227350 0332227830 0332227710 0332227900 0332227910 0332227920 M0332228070	49-23-00-350-802, REPAIR 06 49-23-00-350-816, REPAIR 26 49-23-00-320-803, REPAIR 05 49-23-00-360-802, REPAIR 15	Scroll	C7
Hamilton Sundstrand Poland	APS 3200	0332228070, 4508034, 0332227350 0332227830 0332227710 0332227900 0332227910 0332227920 M0332228070, 4508310	49-23-00-340-801, REPAIR 17	Scroll	C7
Hamilton Sundstrand Poland	APS 3200	M0332228070, 4508034 4508310	49-23-00-310-811, REPAIR 40	Scroll	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A	4506289 series	49-23-02-310-801, REPAIR 11 SB-4505000-49-22	Back Face Seal	C7
Hamilton Sundstrand Poland	APS 2600A APS 2600M APS 2600E	4506289 4506289A	49-23-02-310-801, REPAIR 11	Back Face Seal	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Page: Page: 2 – 8 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	4502553 4501370 4502107 4501371 4501371A	49-10-00-360-802, REPAIR 07 49-10-00-360-810, REPAIR 22 49-10-00-360-812, REPAIR 24 49-10-00-350-803, REPAIR 25	Duct Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4502553 4502107 4501371 4501371A	49-10-00-360-804, REPAIR 12	Duct Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4501584 0332427140, 0332427110	49-21-00-350-836, REPAIR 78	Containment Shield	C7
Hamilton Sundstrand Poland	APS 3200	0332427140, 0332427110, 4501584, 0332267080, 0332267210, 0332267360, 4503344, 4507776, M4503344-1, M4503344-2	49-21-00-350-857, REPAIR-78-01	Shielding Ring & Compressor Housing	C7
Hamilton Sundstrand Poland	APS 3200	4950370 4950809 4950811 4950371 4950810 4950812	49-21-10-350-807, REPAIR 20 49-21-10-350-802, REPAIR 03	Main Manifold	C7



Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 9 / 43

Maintenance Capability List

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	0332227370, 0332227390, 0332227400, 0332227720, 0332227730, 0332227740, 0332227960, 0332228010, 0332228050,	49-10-00-350-801, REPAIR 03 49-10-00-360-801, REPAIR 04 49-10-00-360-809, REPAIR 20 49-10-00-360-805, REPAIR 15 49-10-00-360-819, REPAIR 33 49-10-00-360-808, REPAIR 19 49-10-00-360-806, REPAIR 17 49-10-00-360-817, REPAIR 31 49-10-00-360-816, REPAIR 30 49-10-00-360-823, REPAIR 38	Air Inlet Plenum / Upper Half Lower Half	C7
Hamilton Sundstrand Poland	APS 3200	0332227370, 0332227400, 0332227720, 0332227740, 0332228010, 0332228050,	49-10-00-360-813, REPAIR 26	Air Inlet Plenum	C7
Hamilton Sundstrand Poland	APS 3200	0332227370, 0332227390, 0332227720, 0332227730, 0332227960, 0332228050,	49-10-00-360-818, REPAIR 32	Air Inlet Plenum	C7
Hamilton Sundstrand Poland	APS 3200	0332227370, 0332227720, 0332228050,	49-10-00-360-805, REPAIR 15	Air Inlet Plenum	C7
Hamilton Sundstrand Poland	APS 3200	0332227880 0332227820	49-10-00-360-815, REPAIR 28	Air Intake Screen	C7



Revision: 155

Date: December 09, 2024

Chapter - Page: 2 – 10 / 43

Maintenance Capability List

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2600A	4505168 D	49-26-02-310-801, REPAIR 02 49-26-02-380-801, REPAIR 03	Gearbox Housing	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600M	4506256 A/B	49-22-01-350-801, REPAIR 01 49-22-01-310-801, REPAIR 02 49-22-01-350-803, REPAIR 03	Air Inlet Housing	C7
Hamilton Sundstrand Poland	APS 2600A	4506256 B	49-22-01-350-801, REPAIR 01 49-22-01-310-801, REPAIR 02	Air Inlet Housing	C7
Hamilton Sundstrand Poland	APS 3200	756461, -A 757259, -A, -B 4520405	49-26-00-350-804, REPAIR 20	Gearbox Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4101150A, -B, -C	49-52-04-350-801-A, REPAIR 01 49-52-04-350-803-A, REPAIR 03 49-52-04-350-811-A, REPAIR 11 49-52-04-350-812-A, REPAIR 12	Cooling Fan Housing	C7
Hamilton Sundstrand Poland	APS 5000	7004996	49-20-02-350-806, Repair 12	Bellmouth	C7
Hamilton Sundstrand Poland	APS 3240A APS 3240E	4507419 4507420A	49-20-00-360-803	Cooling Fan Duct	C7
Hamilton Sundstrand Poland	APS 3240A	4507419	PP5225 49-20-00	Cooling Fan Duct	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 11 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2600A	4506258 B	49-23-01-310-802, REPAIR 05	Compressor Shroud	C7
Hamilton Sundstrand Poland	APS 5000	7001276A, 7001276B	49-20-02-350-805, REPAIR 11	Diffuser Support Housing Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4520392, 4520393	4510733_CIR_Rev.14_FEB.14,2019 49-10-00-350-801, Repair 03 49-10-00-360-801, Repair 04 49-10-00-360-805, Repair 15 49-10-00-310-806, Repair 16 49-10-00-310-806, Repair 17 49-10-00-360-807, Repair 18 49-10-00-360-808, Repair 19 49-10-00-360-809, Repair 20 49-10-00-360-816, Repair 30 49-10-00-360-817, Repair 31 49-10-00-360-813, Repair 26 49-10-00-360-819, Repair 33	Lower Plenum / Plenum Assy	C7
Hamilton Sundstrand Poland	APS 3200	01R4504086	TEST 49-23-05-700-801-A 49-23-05-350-801-A01, REPAIR 01 49-23-05-350-802-A01, REPAIR 02 49-23-05-350-803-A01, REPAIR 03 49-23-05-330-801-A01, REPAIR 04 49-23-05-350-804-A01, REPAIR 05 49-23-05-350-805-A01, REPAIR 06 49-23-05-350-806-A01, REPAIR 07 49-23-05-350-807-A01, REPAIR 08 49-23-05-350-808-A01, REPAIR 09	Inlet Guide Vane Actuator Assembly	C7



Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 12 / 43

Maintenance Capability List

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	0332227420, 0332227640, 0332227430, 0332227950, 4507942, 4508518	49-23-10-360-801, REPAIR 01 49-23-10-390-801, REPAIR 04 49-23-10-380-801, REPAIR 05 49-23-10-310-801, REPAIR 06 49-23-10-310-802, REPAIR 10 49-23-10-340-801, REPAIR 12	Air Inlet Housing	C7
Hamilton Sundstrand Poland	APS 3200	0332267080, 0332267210, 0332267360, 4503344, M4503344-1, M4503344-2, 4507776	49-21-00-310-812, REPAIR 38 49-21-00-350-858, REPAIR-38-01	Compressor Housing	C7
Hamilton Sundstrand Poland	APS 5000	4500577	APS5000-49-012A	Modification plate	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APU APS3200 APS 3240A APS 5000 APS 2600M APS 2600E	ALL	49-00-01-350-805, REPAIR 16	Repair process was performed on Compressor diffuser PN 4506279A	C7
Hamilton Sundstrand Poland	APS 500R	4503141B, -C	SB 4504616-49-2	Fuel Control Housing	C7
Hamilton Sundstrand Poland	APS 3240A	4507959; 4507959A	49-20-00-350-802, REPAIR 18	Air Inlet Screen Assy	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 13 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 5000	7002584	49-22-01-310-801, REPAIR 01 49-22-01-350-801, REPAIR 02 49-22-01-350-803, REPAIR 04 HSPS PRM-1, REPAIR 260 49-22-01-350-804, REPAIR 05	Air Inlet Housing	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 3200 APS 5000 APS 3240A APS 2600M APS 2600E	ALL	49-00-01-350-803, REPAIR 08	Repair process was performed on Containment Shield PN 4501584	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 3200 APS 3240A APS 5000 APS 2600M APS 2600E	ALL	49-00-01-350-801, REPAIR 01	Repair process was performed on Scroll PN 4508034	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 3200 APS 3240A APS 5000 APS 2600M APS 2600E	ALL	49-00-01-380-802, REPAIR 03	Repair process was performed on Bearing Support Assy PN 4505552, 0332227310	C7
Hamilton Sundstrand Poland	APS 2300 APS 3200 APS 5000 APS 2600A APS 3240A APS 2600M APS 2600E	ALL	49-00-01-350-814, REPAIR 22	Repair process was performed on Collector PN 7003096-1, 7003096-4	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 14 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2300 APS 3200 APS5000 APS 2600A APS 3240A APS 2600M APS 2600E	ALL	49-00-01-350-807, REPAIR 18	Repair process was performed on Air Inlet Housing PN 4506256	C7
Hamilton Sundstrand Poland	APS 2300 APS 3200 APS 5000 APS 2600A APS 3240A APS 2600M APS 2600E	ALL	49-00-01-350-808, REPAIR 19	Repair process was performed on Air Inlet Housing PN 4506256	C7
Hamilton Sundstrand Poland	APS 3200	4502620, 4502497, 4502620A, 4502497A, 4502620B, 4502620C	49-21-10-350-804, REPAIR 12	Combustor Housing	C7
Hamilton Sundstrand Poland	APS 3200	4502108, -A	49-10-00-310-802, REPAIR 06 49-10-00-310-808, REPAIR 29	Tailpipe Assy	C7
Hamilton Sundstrand Poland	APS 5000	7005300	49-20-01-350-805, REPAIR 08	Shield Assembly, Fuel Module	C7
Hamilton Sundstrand Poland	APS 3200	4101150B, -A, -C	49-52-04-350-817-A, REPAIR 17	Cooling Fan Assembly	C7
Hamilton Sundstrand Poland	APS 5000	7003096-1, 7003096-4	49-92-02-350-801, REPAIR 01 49-92-02-350-802, REPAIR 02 49-92-02-310-801, REPAIR 03	Collector	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 15 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2600E	4510365 series	49-22-01-350-801-A, REPAIR 01 49-22-01-310-801, REPAIR 02 49-22-01-350-803-A, REPAIR 03	Air Inlet Housing	C7
Hamilton Sundstrand Poland	APS 2600E	4510145 series	49-23-01-310-802-A, REPAIR 05	Compressor Shroud	C7
Hamilton Sundstrand Poland	APS 2600E	4520341, 4520344	49-22-02-390-801-A, REPAIR 01 49-22-02-360-801-A, REPAIR 03 49-22-02-360-803-A, REPAIR 05 49-22-02-350-801, REPAIR 06 49-22-02-350-802, REPAIR 07 49-22-02-350-804-A, REPAIR 09 49-22-02-350-805-A, REPAIR 10	Air Inlet Plenum	C7
Hamilton Sundstrand Poland	APS 3200	0332207040, 0332207080, 0332207060, 4504434, 0332207100, 0332207090, 4504836	49-23-00-350-801, Repair 01 49-23-00-350-804, Repair 08	Load Compressor Impeller	C7
Hamilton Sundstrand Poland	APS 3200	4504320, 4504834	49-21-00-350-807, Repair 07 49-21-00-350-813, Repair 24	Generator Compressor Impeller	C7
Hamilton Sundstrand Poland	APS 3240A	508034, 4508310, 01R4508034, 4520396, 4520423	49-23-00-350-805, Repair 10	Scroll	C7



Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 16 / 43

Maintenance Capability List

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 5000	7001472B, 7004378A	49-24-03-310-804, REPAIR 3	Containment Ring	C7
Hamilton Sundstrand Poland	APS 5000	7004363	49-20-02-350-803, REPAIR 9	Screen Assembly	C7
Hamilton Sundstrand Poland	APS 2300	4506257, 4506257A	HSPS SB 4505000-49-19 49-24-01-310-801, REPAIR 01 49-24-01-310-803, REPAIR 06	Combustor Housing Assembly	C7
Hamilton Sundstrand Poland	APS 5000	7004472	SBA-APS5000-49-008	1st Stage Nozzle Assembly	C7
Hamilton Sundstrand Poland	APS 3200	0332267160, 4507778	49-21-00-350-817, REPAIR 30 AI-RDE 14192	Diffuser	C7
Hamilton Sundstrand Poland	APS 5000	7003096-3, 7003096-2, 7006474	49-92-02-310-802, REPAIR 04	Fireshield	C7
Hamilton Sundstrand Poland	APS 5000	7001474C, 7004474	49-24-03-340-801, REPAIR 08 Service Bulletin 500078	2nd Stage Nozzle Assembly	C7



Maintenance Capability List

Revision: 149

Date: June 28, 2024

Chapter - Page: 2 – 17 /43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2600A	4507063 series 4508964 series	49-22-02-390-801, REPAIR 01 49-22-02-350-802, REPAIR 03	Air Inlet Plenum	C7
Hamilton Sundstrand Poland	APS 3200	756669 series	49-26-00-040-808, Disassembly 07 49-26-00-440-803, Assembly 02	Start Motor Shaft Assembly	C7
Hamilton Sundstrand Poland	APS 3200	5909974	49-26-00-390-801, REPAIR 09	Oil Fill Tube	C7
Hamilton Sundstrand Poland	APS 3200	5908968, 5909974	49-26-00-310-802, REPAIR 14 49-26-00-390-802, REPAIR 18	Oil Fill Tube	C7
Hamilton Sundstrand Poland	APS 3200	4500039 all series, M4500039 all series, 4500052A, 4503111 all series, 4503841 all series, 4505496	49-32-04-300-815-A01, REPAIR 14	Fuel Control Housing	C7
Hamilton Sundstrand Poland	APS 5000	7005298-4, 7005298-5, 7005298-6, 7005299-1, 7005299-2, 7005299-3	49-20-01-300-804, REPAIR 06	Thermal Blanket	C7
Hamilton Sundstrand Poland	APS 5000	7005108 series, 7001274 series,	49-23-01-380-801, REPAIR 07	Diffuser	C7



Maintenance Capability List

Revision: 156

Date: December 19, 2024

Chapter - Page: 2 – 18 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 5000	7005108 series 7004794 series 7005064, 7004794, 7007191	49-23-01-380-802, REPAIR 08	Shroud	C7
Hamilton Sundstrand Poland	APS 5000	7004608, 7004609	49-20-02-350-804, REPAIR 10	Fuel Manifold Fire Sleeves	C7
Hamilton Sundstrand Poland	APS 3200	0332220840	49-23-10-350-803, REPAIR 9 49-23-10-380-803, REPAIR 15	Gear Ring Support	C7
Hamilton Sundstrand Poland	APS 5000	7004744, 7004744A	49-22-02-350-807, REPAIR 10	Air Inlet Plenum Assembly	C7
Hamilton Sundstrand Poland	APS 5000	7004744A	49-22-02-350-808, REPAIR 11	Air Inlet Plenum Assembly	C7
Hamilton Sundstrand Poland	APS 3200	0332227980, 0332227990, 0332228000, 0332228030, 0332228040	49-10-00-360-829, REPAIR 39	Plenum Partitions	C7
Pratt & Whitney	APS 500R	ALL	49-00-01-350-801, REPAIR 01	APS500	C7
Pratt & Whitney	APS 500R	ALL	49-00-01-380-802, REPAIR 03	APS500	C7



Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 19 / 43

Maintenance Capability List

Make	Model	Part Number	Repair Number	Description	EASA Rating
Pratt & Whitney	APS 500R	ALL	49-00-01-350-807, REPAIR 18	APS500	C7
Pratt & Whitney	APS 500R	ALL	49-00-01-350-808, REPAIR 19	APS500	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A	4506222, 4508591	49-22-03-350-801, REPAIR 01	Ring Assembly	C7
Hamilton Sundstrand Poland	APS 5000	7005106, 7005105, 7005104, 7005103, 7005102, 7004320-3, 7004320-2, 7001105, 7002792, 7002775, 7005302, 7004297, 7002793, 7000549A, 7001383A, 7000723A, 7003629, 7003538-2, 7003538-1, 7004743-5, 7000714, 7000717, 7000719, 7004901	49-14-02-300-801, REPAIR 01	Accessory Bracket	C7
Hamilton Sundstrand Poland	APS 3240A	4507386A, 4507387B, 4507387C; 4507386B	49-20-00-390-801, Repair 12	Upper & Lower Half Plenum Assembly	C7
Hamilton Sundstrand Poland	APS 2300	4505265	49-24-03-350-802, Repair 13	Support Ring	C7



Maintenance Capability List

Revision: 146

Date: June 03, 2024

Chapter - Page: 2 – 20 / 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2300 APS 2600M APS 2600E APS 2600A	4505111, 4505111A, 4505111B	49-24-03-350-801, REPAIR 05	Containment Shield Assembly	C7
Hamilton Sundstrand Poland	APS 5000	7001346A	49-20-02-340-801, REPAIR 06 49-20-02-340-802, REPAIR 07 49-20-02-350-802, REPAIR 08	Shroud Assembly	C7
Hamilton Sundstrand Poland	APS 3200	0332227400, 0332227740, 0332228010	49-10-00-360-820, REPAIR 34	Upper Half Plenum Assembly	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M APS 2600E APS 3200 APS 3240A APS 5000	ALL	49-00-01-360-809, Repair 35	Repair process was performed on Plenum Assembly PN4951881	C7
Hamilton Sundstrand Poland	APS APS5000	7000066A 7900050 7900001	49-26-02-350-801, REPAIR 05 49-26-02-380-801, REPAIR 03	Gearbox Assembly	C7
Hamilton Sundstrand Poland	APS 5000 APS 2300 APS 2600 APS 3400 APS 3240 APS 3200	ALL	SPM HSPS 490001 49-00-01-350-802, Repair 07	Removal of the Nicks, the scratches and the Burrs.	C7
Hamilton Sundstrand Poland	APS 3240A APS 3240 E	4507919	49-20-00-310-803, Repair 17 49-20-00-310-801, Repair 14 49-20-00-310-802, Repair 15	Inseparable Tailpipe Assembly	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 21/ 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 5000	7000103 all series	SB APS-49-500061	Air Oil Separator Gear	C7
Hamilton Sundstrand Poland	APS 3200	4503344, M4503344-1, M4503344-2, 4507776	49-21-00-340-808, REPAIR 64	Compressor Housing	C7
Hamilton Sundstrand Poland	APS 3200	0332267150	49-23-00-350-823, Repair 46	Support	C7
Hamilton Sundstrand Poland	APS 5000	7001576B, 7004477, 7006653	49-81-01-350-802, REPAIR 07	Exhaust Housing	C7
Hamilton Sundstrand Poland	APS 3200	0332227070, 0332227060, 0332227640, 0332227430, 0332227950, 4507942, 4508518	49-23-10-360-801, REPAIR 01	Inlet Hub / Assembly Inlet Housing	C7
Hamilton Sundstrand Poland	APS 3200	4502108, 4502108A, 4501790, 4504080	49-10-00-310-803, REPAIR 09 49-10-00-310-805, REPAIR 11	Tailpipe Assembly	C7
Hamilton Sundstrand Poland	APS 3240A APS 3240 E	4508477	49-21-00-350-808, Repair 21 49-21-00-350-807, Repair 20	Generator Compressor Impeller	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 22/ 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	0332227370, 0332227720, 0332228050, 0332227400, 0332227740, 0332228010, 0332227390, 0332227730, 0332227960	49-10-00-310-8SB06, Repair 16	Plenum Assembly	C7
Hamilton Sundstrand Poland	APS 3200	0332220810, 0332222420, 4504274	49-23-10-350-801, REPAIR 07	Gear Ring	C7
Hamilton Sundstrand Poland	APS 3200	4950370, 4950811, 4950809, 4950371, 4950810, 4950812	49-21-10-350-809, Repair 31 RDTI 3200492110-TI-171025.1	Primary Fuel Manifold & Secondary Fuel Manifold	C7
Hamilton Sundstrand Poland	APS 2300	4951708, 4951707	49-31-04-350-803, REPAIR 03 49-31-05-350-803, REPAIR 03	Primary Fuel Manifold & Secondary Fuel Manifold	C7
Hamilton Sundstrand Poland	APS 3240A	4508310 4508034	SB APS-49-327042	Scroll Assembly	C7
Hamilton Sundstrand Poland	APS 3200	0332227410 0332227880 0332227820	49-10-00-360-830	Air Inlet Screen	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 23/ 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	757259, -A, -B	49-26-00-320-808, Repair 12	Gearbox Housing Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4950242; 4950862; 4950882; 4951093; M4950862; 4951652; M4950242	49-91-11- 350-805-A, Repair 05 49-91-03-350-807-A01, Repair 07 49-91-11-350-807-A01, Repair 07	Oil Cooler	C7
Hamilton Sundstrand Poland	APS 3200	4950242; M4950242, M4950862, 4950862, 4950882, 4951093	49-91-03-350-804-A01, Repair 04	Oil Cooler	C7
Hamilton Sundstrand Poland	APS 3200	4520482 4520522 4520521 4520520	49-21-00-350-804, REPAIR 04 49-21-00-350-805, REPAIR 05 49-21-00-350-806, REPAIR 06	Disk assembly, turbine – second stage	C7
Hamilton Sundstrand Poland	APS 3200	4501105; 4501105A, 4502620, 4502497, 4502620A, 4502497A, 4502620B	49-21-10-310-809, Repair 17	Combustor Housing	C7
Hamilton Sundstrand Poland	APS 3200	757259, 757259A, 757259B	SB-49-320153	Gearbox Assy	C7
Hamilton Sundstrand Poland	APS 3200	756660	SB-49-320153	Cover	C7
Hamilton Sundstrand Poland	APS 5000	7005302	49-14-02-310-801, Repair 03	Bracket, Accessory - Isolating	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 24/ 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 5000	7003545 7006317 7900170	49-31-04-350-801, Repair 1	Primary and secondary fuel manifold	C7
Hamilton Sundstrand Poland	APS 5000	7003793 7006318 7900171	49-31-05-350-801, Repair 1	Primary and secondary fuel manifold	C7
Hamilton Sundstrand Poland	APS 5000	7004743B 7004744 7004744A	49-22-02-390-802, REPAIR 01 49-22-02-350-801, REPAIR 02 49-22-02-360-801, REPAIR 03 49-22-02-360-802, REPAIR 04 49-22-02-350-802, REPAIR 05 49-22-02-350-803, REPAIR 06 49-22-02-350-806, REPAIR 09 49-22-02-350-805, REPAIR 08 49-22-02-350-804, REPAIR 07	Air Inlet Plenum	C7
Hamilton Sundstrand Poland	APS 5000	7002584 7007119 7900169	49-22-01-310-801, REPAIR 01 49-22-01-350-801, REPAIR 02 49-22-01-350-803, REPAIR 04 49-22-01-350-803, REPAIR 05 PRM-1 REPAIR 260	Air Inlet Housing Assembly	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 25/ 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 5000	7001795 7003596 7900095	49-23-02-380-801, REPAIR 05	Compressor Impeller	C7
Hamilton Sundstrand Poland	APS 3240E	4507419	APU position Paper No.:5225	Air Inlet – Cooling Fan Duct Assy	C7
Hamilton Sundstrand Poland	APS 5000	7005300	49-20-01-350-804, REPAIR-07	Fuel Module – Shield Assembly	C7
Hamilton Sundstrand Poland	APS 5000	7000723A	49-14-02-350-801, Repair 04	AFT Mount Bracket	C7
Hamilton Sundstrand Poland	APS 5000	7001584, 7007106	49-23-02-230-805 49-23-02-210-811 Cleaning according with 490001 SPM 49-00-01-110-815	Tie Bolt	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600 E	4506279A	49-23-01-350-801, Repair 02	Compressor Diffuser Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4501371; 4501371A; 4502553; 4501370; 4502107; 4500587; 4500587A; 4500587B	49-10-00-360-804, Repair 12 49-10-00-360-802, Repair 07	Duct Assembly	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 26/ 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	0332207040, 0332207080, 0332207060, 0332207100, 4504434, 0332207090, 4504836	49-23-00-350-805, Repair 09	Load Compressor Impeller	C7
Hamilton Sundstrand Poland	APS 3200	4500039 all series; M4500039 all series; 4510833; 4520455; 4500052A; 4503111 all series; 4509711; 4503841 all series; 4505496; 4509712	49-32-04-300-815-A01, Repair 14	Fuel Control Assembly / Fuel Control Housing	C7
Hamilton Sundstrand Poland	APS 3240A	4507338	49-23-10-350-804, Repair 08	Bearing Support	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600E APS 2600M APS 3200 APS 3240A APS 3240E APS 5000	All	SPOP 533, TASK PWSPM-D-70-45- 00-01A-642A-D	Removal of the Nicks, the scratches and the Burrs	C7
Hamilton Sundstrand Poland	APS 3240A	4507420A	49-20-00-360-804, Repair 04	Duct Assmebly	C7



Maintenance Capability List

Revision: 155

Date: December 09, 2024

Chapter - Page: 2 – 27/ 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3240A APS 3240E	4507419, 4507420A,	49-20-00-360-806, Repair 06	Duct Assembly	C7
Hamilton Sundstrand Poland	APS 3240A APS 3240E	4507419, 4507420A	49-20-00-360-805, Repair 05	Duct Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4950000	Inspection Task 49-10-00-210-806 (Only visual check of the exciter, except functional test).	Exciter	C7
Hamilton Sundstrand Poland	APS 3200	4951652	49-91-11-350-809-A01, Repair 09	Oil Cooler	C7
Hamilton Sundstrand Poland	APS 3240A	756461A, 4507291, 4508670,	49-26-00-350-806, Repair 09	Housing Assy, Gearbox -matched set	C7
Hamilton Sundstrand Poland	APS 3240 A APS 3240 E	4953002	49-92-08-350-003-A01, Repair 03 49-92-08-350-004-A01, Repair 04 RDTI3240499208-TI-220727.1 49-92-08-350-005-A01, Repair 05	Oil Cooler	C7
Hamilton Sundstrand Poland	APS 3240 A	0332227420;0332227640; 0332227430;0332227950; 4507942; 4508518;	49-23-10-350-803, Repair 05 49-23-10-310-801, Repair 06 49-23-10-340-802, Repair 07	Air Inlet Housing	C7
Hamilton Sundstrand Poland	APS 3200	0332267330	49-21-00-390-801, Repair 31	Support Bracket	C7
Hamilton Sundstrand Poland	APS 3200	756461A 757259 -A,-B 01R757259 -A,-B 4520405	49-26-00-360-801	Gearbox Housing	C7



Maintenance Capability List

Revision: 147

Date: June 18, 2024

Chapter - Page: 2 – 28/ 43

Make	Model	Part Number	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2300	4506256 series	49-22-01-350-806, Repair 07	Air Inlet Housing	C7
Hamilton Sundstrand Poland	APS 2600 E	4506284, 4507017, 4520419	49-23-02-350-843, Repair 19	1st Stage Turbine Disk	C7
Hamilton Sundstrand Poland	APS 2600 E	4510191	49-23-01-340-805, Repair-10	Fairing - Inlet Compressor	C7
Hamilton Sundstrand Poland	APS 5000	7001276A, 7001276B	49-20-02-350-801, REPAIR-03	Diffuser Support Housing Assembly	C7
Hamilton Sundstrand Poland	APS 2600E APS 2600A	4505052C	49-81-01-210-005, Subtask	DUCT ASSY, EXHAUST, TURBINE INSEPERABLE	C7
Hamilton Sundstrand Poland	APS 5000	7002123	49-24-03-310-807, REPAIR 07	1st Stage Attachement	C7
Hamilton Sundstrand Poland	APS 2600 E	4520344	49-22-02-350-808, Repair 13	Air Inlet Plenum, Bottom Half	C7
Hamilton Sundstrand Poland	APS 2600 E	4510366 series	49-22-01-350-806, Repair 07	Inlet Housing Assembly	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 29/ 43

Place intentionally left blank



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 30/ 43

2.2 LRU PARTS NUMBER

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200 APS 3240A APS 3240E	5909073	A 320 EM A 340 EM APS3240-1 EM A 320 CIR	49-26-00-750-802, TEST 02 49-26-00-210-003, SUBTASK	Oil Temperature Sensor	C7
Hamilton Sundstrand Poland	APS 3200	4950488 4951985	A 320 EM A 320 CIR	49-10-00-750-802, TEST-03	Low Oil Pressure Switch	C7
Hamilton Sundstrand Poland	APS 3200 APS 3240A APS 3240E	5909849	A 320 EM A340 EM APS3240-1 EM	49-26-00-750-801, TEST-01	Oil Level Sensor	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M	4951693 series	ACMM 49-40-03	49-40-03-750-001-A01, TEST	Igniter Cable Assembly	C7
Hamilton Sundstrand Poland	APS2300 APS2600A APS2600M	4951690 series	ACMM 49-70-20 CIR 2300-2	49-70-20-810-801-A, TESTING 49-10-01-350-801, REPAIR-01	Thermocouples	C7
Hamilton Sundstrand Poland	APS 3200	4950944 4951546	A 320 EM A 320 CIR	49-10-00-750-801, TEST-01 49-10-00-350-802, REPAIR-14	Compressor Discharge Pressure Sensor	C7
Hamilton Sundstrand Poland	APS 3240A	4951546	APS3240-1 EM	49-20-00-750-805, TEST	Compressor Discharge Pressure Sensor	C7
Hamilton Sundstrand Poland	APS 3200	4952590	A 320 EM	49-10-00-750-807, TEST-08	Compressor Discharge Pressure Sensor	C7

HAMILTON SUNDSTRAND POLAND SP. Z O.O. PROPRIETARY INFORMATION. USE OR DISCLOSURE OF INFORMATION ON THIS PAGE IS SUBJECT TO THE NOTICE OF RESTRICTIONS ON THE FIRST PAGE OF THIS DOCUMENT



Maintenance Capability List

Revision: 151

Date: August 08, 2024

Chapter - Page: 2 – 31/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3240A	4952590	APS3240-1 EM	49-10-00-750-807, TEST	Compressor Discharge Pressure Sensor	C7
Hamilton Sundstrand Poland	APS 2300 APS 3240A APS 2600M APS 3400	4951695	CMM 49-90-22	49-90-22-700-801-A, TEST	Dual Oil Pressure Sensor	C7
Hamilton Sundstrand Poland	APU APS3200	4950036	A 320 EM A 320 CIR	49-10-00-750-804, TEST-05 49-10-00-360-821, REPAIR-35	Inlet Pressure/Temperature Sensor	C7
Hamilton Sundstrand Poland	APS 3240A	4950036	APS3240-1 EM APS3240 CIR	49-20-00-750-803, TEST 49-20-00-360-807, REPAIR-08	Inlet Pressure/Temperature Sensor	C7
Hamilton Sundstrand Poland	APS 3200	4502242 series 4504986 series 4506061 series 4500062 4502023 series M4502242C series M4504986 series M4506061 series	CMM 49-10-04 CMM 49-10-06	49-10-06-700-801-A, TESTING 49-10-06-350-801-A, REPAIR-01 49-10-06-350-803-A, REPAIR-03 49-00-01-350-810, REPAIR-29 49-10-06-350-805-A, REPAIR-05 49-10-06-350-802-A, REPAIR-02 49-10-06-350-806-A, REPAIR-06 49-10-06-350-807-A, REPAIR-07 49-10-06-350-804-A, REPAIR-04 49-10-06-350-808-A, REPAIR-08 49-10-06-350-809-A, REPAIR-09 49-10-06-350-810-A, REPAIR-10 49-10-06-350-811-A, REPAIR-11 49-10-06-350-812-A, REPAIR-12 49-10-06-350-813 A01, REPAIR-13 49-10-04-700-801-A, TESTING	Engine Harness Assembly	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 32/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	4502242 series 4504986 series 4506061 series 4500062 4502023 series M4502242C series M4504986 series M4506061 series	CMM 49-10-04 CMM 49-10-06	49-10-04-350-801-A, REPAIR 01 49-10-04-350-802-A, REPAIR 02 49-10-04-350-803-A, REPAIR 03 49-10-04-350-812-A, REPAIR 12 49-10-04-350-804-A, REPAIR 04 49-10-04-350-805-A, REPAIR 05 49-10-04-350-806-A, REPAIR 06 49-10-04-350-807-A, REPAIR 07 49-10-04-350-808-A, REPAIR 08 49-10-04-350-809-A, REPAIR 09 49-10-04-350-810-A, REPAIR 10 49-10-04-350-811-A, REPAIR-11	Engine Harness Assembly	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M	4950760 4953999	ACMM 49-90-21	49-90-21-700-801-A, TEST	Oil Temperature Sensor	C7
Hamilton Sundstrand Poland	APS 5000	7000098H01	ACMM 49-93-11	49-93-11-700-801-A, TEST	Oil Temperature Sensor	C7
Hamilton Sundstrand Poland	APS 3200	4101252 series 4101184 series M4101252 series M4101184 series 4510836 4510837	CMM 49-23-02	49-23-02-700-801-A01, TESTING 49-23-02-350-801-A01, REPAIR NO.1 49-23-02-350-804-A01, REPAIR NO.4 49-23-02-350-805-A01, REPAIR NO.5 49-23-02-350-806-A01, REPAIR NO.6	BCV Actuator assembly - valve	C7
Hamilton Sundstrand Poland	APS 3200	4101184 series M4101184 series	CMM 49-23-02	AI RDE12046, Repair-07	BCV Actuator assembly - valve	C7
Hamilton Sundstrand Poland	APS 3200	4101252 series; 4101184 series; M4101252 series; M4101184 series; 4510836; 4510837	CMM 49-23-02	49-23-02-350-802-A01, Repair No.2	Bleed Control Valve Actuator	C7



Maintenance Capability List

Revision: 154

Date: November 18, 2024

Chapter - Page: 2 – 33/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	4100836 series 4100837 series M4100837 series 01R4100837E 01R4100837G 01RM4100837B 01RM4100837C 01RM4100837D 4520451	CMM 49-53-02	49-53-02-700-801-A01, TESTING 49-53-02-300-802-A01, REPAIR NO.1 49-53-02-300-803-A01, REPAIR NO.2 49-53-02-300-804-A01, REPAIR NO.3 49-53-02-300-805-A01, REPAIR NO.4 49-53-02-300-806-A01, REPAIR NO.5	Bleed Control Valve	C7
Hamilton Sundstrand Poland	APS 3200	4954220	EM 4510732	49-10-00-750-802, TEST	Low Oil Pressure Switch	C7
Hamilton Sundstrand Poland	APS 3200	4508693 4520391	CMM 49-70-05	49-70-05-700-801, TESTING	Engine Serial Number Identification Assembly	C7
Hamilton Sundstrand Poland	APS 5000	7000457H01 7000456H02	CMM	CMM 49-31-31 CMM 49-31-30 SI 123-2018	Injector Assy, Fuel Simplex Injector Assy, Fuel Duplex	C7
Hamilton Sundstrand Poland	APS 3240A APS 3240 E	4952676	CIR 3240A CIR 3240 E	49-21-10-220-808	Injector Pilot Fuel Assembly	C7
Hamilton Sundstrand Poland	APS 5000	7000898H02	CMM 49-31-22	49-31-22-700-801-A, TESTING	Inseparable PMG Stator Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4520452 4520615	CMM 49-52-04	49-52-04-700-801-A01, TESTING 49-52-04-350-801-A01, REPAIR 01 49-52-04-350-804-A01, REPAIR 04 49-52-04-350-806-A01, REPAIR 06 49-52-04-350-807-A01, REPAIR 07 49-52-04-350-818-A01, REPAIR 18	Cooling Fan Assembly	C7



Maintenance Capability List

Revision: 154

Date: November 18, 2024

Chapter - Page: 2 – 34/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3240A APS 3240E	4507320 series 4520463	CMM 49-50-06	49-50-06-700-801-A, TESTING 49-50-06-320-002-A01, REPAIR 49-50-06-320-003-A01	Bleed Control Valve Assembly	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 3200 APS 3240A APS 2600M APS 3240E	756722 series	CMM 49-92-01	49-92-01-700-002-A01, TEST	Solenoid Valve Assembly	C7
Hamilton Sundstrand Poland	APS 3200 APS 3240A APS 3240E	4504086 series	CMM 49-23-05	49-23-05-700-801-A, TEST 49-23-05-350-801-A01, REPAIR-01 49-23-05-350-802-A01, REPAIR-02 49-23-05-350-803-A01, REPAIR-03 49-23-05-350-804-A01, REPAIR-05 49-23-05-350-805-A01, REPAIR-06 49-23-05-350-806-A01, REPAIR-07 49-23-05-350-807-A01, REPAIR-08 49-23-05-350-010-A01, REPAIR-09	Inlet Guide Vane Actuator Assembly	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M	4505008 series	CMM 49-31-20	49-31-20-700-801, TEST 49-31-20-380-801, REPAIR-01 49-31-20-350-801, REPAIR-02 49-31-20-350-802, REPAIR-03 49-31-20-320-801, REPAIR-04 49-31-20-320-802, REPAIR-05 49-31-20-350-804, REPAIR-07	Fuel Module Assembly	C7
Hamilton Sundstrand Poland	APS 3200 APS 3240A APS 3240E	4501259 series 4520610	CMM 49-33-01	49-33-01-700-801-A, TEST	Flow divider assembly	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 35/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	4101098 series 4101099 series	CMM 49-52-04	49-52-04-700-801-A TESTING 49-52-04-350-801-A01 REPAIR 01 49-52-04-350-804-A01 REPAIR 04 49-52-04-350-806-A01 REPAIR 06 49-52-04-350-807-A01 REPAIR 07 49-52-04-350-818-A REPAIR 18	Cooling Fan Assembly	C7
Hamilton Sundstrand Poland	APS 3240A APS 3240A	4507423 series	CMM 49-52-09	49-52-09-700-801-A, TESTING 49-52-09-350-801-A, REPAIR NO.1 49-52-09-350-802-A, REPAIR NO.2 49-52-09-350-803-A, REPAIR NO.3 49-52-09-350-804-A, REPAIR NO.4 49-52-09-350-805-A, REPAIR NO.5	Cooling Fan Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4500039 SERIES M4500039 SERIES	CMM 49-32-04	49-32-04-700-801-A01, TESTING 49-32-04-300-803-A01, REPAIR 49-32-04-300-804-A01, REPAIR 49-32-04-300-807-A01, REPAIR 49-32-04-300-809-A01, REPAIR 49-32-04-300-812-A01, REPAIR 49-32-04-300-813-A01, REPAIR 49-32-04-300-815-A01, REPAIR 49-32-04-300-816-A01 REPAIR NO. 15	Fuel Control Assembly	C7
Hamilton Sundstrand Poland	APS 3200 APS 3240A	4504086 series; 4510835	CMM 49-23-05	49-23-05-330-801-A01, Repair No. 4	Inlet Guide Vane Actuator	C7
Hamilton Sundstrand Poland	APS 3240E	4504086 series	CMM 49-23-05	49-23-05-330-801-A01, Repair No. 4	Inlet Guide Vane Actuator	C7



Maintenance Capability List

Revision: 144

Date: March 18, 2024

Chapter - Page: 2 – 36/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	4950009	A 320 EM A 320 CIR	49-10-00-750-805, TEST 49-10-00-210-810, INSPECTION	Speed Sensor	C7
Hamilton Sundstrand Poland	APS 3240A	4950009, 4952657, 4954260, 4954293	EM APS 3240 CIR APS 3240	49-20-00-750-801, TEST 49-20-00-280-801, INSPECTION	Speed Sensor	C7
Hamilton Sundstrand Poland	APS 3240A	4952657	A340 EM	49-20-00-750-801, TEST-01 49-20-00-280-801, I/C-09	Speed Sensor	C7
Hamilton Sundstrand Poland	APS 3200 APS 3240A APS 3240E	4950136, 4952164	CMM 49-41-07	CMM 49-41-07, TESTING CMM 49-41-07, REPAIR-01 CMM 49-41-07, REPAIR-02 CMM 49-41-07, REPAIR-03 CMM 49-41-07, REPAIR-05 CMM 49-41-07, REPAIR-06	Starter	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600A	4951694	CMM 49-70-10	49-70-10-700-801-A, TEST	Dual Coil Speed Sensor	C7
Hamilton Sundstrand Poland	APS 3240A	4954086	CMM PP 5343 SB- APS-49-327023	Reprogramming DMM per listed documentation (CMM PP 5343 SB-APS-49-327023)	Data memory Module Assy	C7
Hamilton Sundstrand Poland	APS 3240E	4520514, 4508950B	CMM 49-32-22	49-32-22-700-801-A, TESTING 49-32-22-350-001-A01, REPAIR	Fuel Control Unit	C7
Hamilton Sundstrand Poland	APS 3240E	4510834 4510834A	CMM 49-32-26	49-32-26-700-801-A, TESTING 49-32-26-300-802-A, REPAIR NO.1 49-32-26-300-803-A, REPAIR NO.2 49-32-26-300-807-A, REPAIR NO.6 49-32-26-300-808-A, REPAIR NO.7	Main Fuel Pump Assembly	C7



Maintenance Capability List

Revision: 156

Date: December 19, 2024

Chapter - Page: 2 – 37/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	4950597 series	A 320 EM A 320 CIR	49-10-00-750-806, TEST 49-70-00-320-801, REPAIR 01	Thermocouple	C7
Hamilton Sundstrand Poland	APS 5000 APS 2600E	7000151 series	ACMM 49-72-01	49-72-01-700-801-A, TEST	EGT Thermocouple Assembly	C7
Pratt & Whitney Canada, Inc.	PW 980A	4505919 series 3901255-10	CMM 49-32-51 HSPS 490001	49-32-51-700-801, TEST 49-32-51-320-002, REPAIR 49-32-51-350-001, REPAIR 49-32-51-350-002, SUBTASK	Fuel Control Unit	C7
Hamilton Sundstrand Poland	APS 3240A	4507435 series	CMM 49-32-22	49-32-22-700-801-A, TESTING 49-32-22-350-001-A01, REPAIR	Fuel Control Unit	C7
Hamilton Sundstrand Poland	APS 3240A	5010206 series	CMM 49-32-26	49-32-26-700-801-A, TESTING 49-32-26-300-802-A, REPAIR NO.1 49-32-26-300-803-A, REPAIR NO.2 49-32-26-300-807-A, REPAIR NO.6 49-32-26-300-808-A, REPAIR NO.7	Main Fuel Pump Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4504400 4508474	A320 EM A320 CIR HSPS 490001	49-21-00-350-812, REPAIR 49-21-00-710-801, TESTING	Rear Bearing Housing	C7



Maintenance Capability List

Revision: 144

Date: March 18, 2024

Chapter - Page: 2 – 38/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3240E	4950597 series	APS3240[E]-1 EM	49-20-00-280-802 I/C-O9 49-20-00-750-802 TEST-02	Thermocouple	C7
Hamilton Sundstrand Poland	APS 3240E	4951546	APS3240E-1 EM	49-20-00-210-805 I/C-05	Compressor Discharge Pressure Sensor	C7
Hamilton Sundstrand Poland	APS 3240E	4950009, 4952657, 4954260, 4954293	APS3240E-1 EM	49-20-00-280-801 I/C-08 49-20-00-750-801 TEST-01	Speed Sensor	C7
Hamilton Sundstrand Poland	APS 3240E	4952657	APS3240E-1 EM	49-20-00-280-801 I/C-08 49-20-00-750-801 TEST-01	Dual Coil Speed Sensor	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600M	4505052 series	CIR PN 4511183	49-81-01-210-005, SUBTASK TEST	Exhaust Duct	C7
Hamilton Sundstrand Poland	APS 3200	4501089A	EM 4510732, CIR 4510733	49-21-10-730-801, TEST	Pilot Nozzle Assembly	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M	4951949	ACMM 49-33-08	49-33-08-700-801-A, TESTING	Duplex Fuel Injector Assembly	C7
Hamilton Sundstrand Poland	APS 3200	4508728 4501230 4501230A	CIR 4510733	49-21-10-220-806, TEST	Injector Main Nozzle Assembly	C7
Hamilton Sundstrand Poland	APS 2300 APS 2600A APS 2600M	4951948	ACMM 49-33-07	49-33-07-700-801-A, TESTING	Simplex Fuel Injector Assembly	C7

HAMILTON SUNDSTRAND POLAND SP. Z O.O. PROPRIETARY INFORMATION. USE OR DISCLOSURE OF INFORMATION ON THIS PAGE IS SUBJECT TO THE NOTICE OF RESTRICTIONS ON THE FIRST PAGE OF THIS DOCUMENT



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 39/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3200	4510833 4520455	CMM 49-32-04	49-32-04-700-801-A01 TESTING 49-32-04-300-803-A01, REPAIR 49-32-04-300-804-A01 REPAIR 49-32-04-300-807-A01, REPAIR 49-32-04-300-809-A01, REPAIR 49-32-04-300-812-A01, REPAIR 49-32-04-300-813-A01, REPAIR 49-32-04-300-815-A01, REPAIR 49-32-04-300-816-A01, REPAIR NO. 15	FUEL CONTROL ASSEMBLY	C7
Hamilton Sundstrand Poland	APS 3200	4510835	CMM 49-23-05	49-23-05-700-801-A01, TESTING 49-23-05-350-801-A01, Repair No. 1 49-23-05-350-802-A01, Repair No. 2 49-23-05-350-803-A01, Repair No. 3 49-23-05-350-804-A01, Repair No. 5 49-23-05-350-805-A01, Repair No. 6 49-23-05-350-806-A01, Repair No. 7 49-23-05-350-807-A01, Repair No. 8 49-23-05-350-010-A01, Repair No. 9	Inlet Guide Vane Actuator	C7
Hamilton Sundstrand Poland	APS 3200	171816-100	CMM 49-70-02	49-70-02-700-801-A, TESTING 49-70-02-300-801-A, REPAIR	ENGINE SERIAL NUMBER IDENTIFICATION ASSEMBLY	C7
Hamilton Sundstrand Poland	APS 3240A APS 3240E	4101252series	CMM 49-23-02	49-23-02-700-801-A01, TESTING 49-23-02-350-801-A01, REPAIR NO.1 49-23-02-350-802-A01, REPAIR NO.2 49-23-02-350-804-A01, REPAIR NO.4 49-23-02-350-805-A01, REPAIR NO.5 49-23-02-350-806-A01, REPAIR NO.6	Actuator Assy – Valve	C7
Hamilton Sundstrand Poland	APS 3240E APS 3240A	4507423 4520459	CMM 49-52-09	49-52-09-700-801-A, Testing 49-52-09-350-801-A, Repair No. 1 49-52-09-350-802-A, Repair No. 2 49-52-09-350-803-A, Repair No. 3 49-52-09-350-804-A, Repair No. 4 49-52-09-350-805-A, Repair No. 5	Cooling Fan Assembly	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 – 40/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 2600E	4510325	CMM 49-31-22	49-31-22-700-801, Test 49-31-22-380-801, Repair 49-31-22-350-801, Repair 49-31-22-350-802, Repair 49-31-22-320-801, Repair 49-31-22-320-802, Repair	Fuel Module Assembly	C7
Hamilton Sundstrand Poland	APS 3240A	4950597 series	APS3240[A]-1-EM APS3240[A]-2- CIR	49-20-00-750-802, TEST 49-20-00-320-801, REPAIR	Thermocouple	C7
Hamilton Sundstrand Poland	APS 3240A	4510837	CMM 49-23-02	49-23-02-700-801-A01, TESTING 49-23-02-350-801-A01, REPAIR NO.1 49-23-02-350-802-A01, REPAIR NO.2 49-23-02-350-804-A01, REPAIR NO.4 49-23-02-350-805-A01, REPAIR NO.5 49-23-02-350-806-A01, REPAIR NO.6	Bleed Control Valve Actuator	C7
Hamilton Sundstrand Poland	APS 3240 A	4520460	CMM 49-32-22	49-32-22-700-801-A, TESTING 49-32-22-350-001-A01, REPAIR	Fuel Control Unit	C7



Maintenance Capability List

Revision: 148

Date: June 24, 2024

Chapter - Page: 2 – 41/ 43

Make	Model	Part Number	Documentation	Repair Number	Description	EASA Rating
Hamilton Sundstrand Poland	APS 3240A	4510835	CMM 49-23-05	TEST 49-23-05-700-801-A, REPAIR-01 49-23-05-350-801-A01, REPAIR-02 49-23-05-350-802-A01, REPAIR-03 49-23-05-350-803-A01, REPAIR-05 49-23-05-350-804-A01, REPAIR-06 49-23-05-350-805-A01, REPAIR-07 49-23-05-350-806-A01, REPAIR-08 49-23-05-350-807-A01, REPAIR	Inlet Guide Vane Actuator	C7
Hamilton Sundstrand Poland	APS 5000	7001014H01	ACMM 49-16-04	49-16-04-700-801-A, TEST	Door Position Switch	C7
Hamilton Sundstrand Poland	APS3240[E]	4950036	APS3240[E]-1 E	49-20-00-750-803, TEST 49-20-00-360-807, REPAIR-08 /	Inlet Pressure/Temperature Sensor	C7
Hamilton Sundstrand Poland	APS 3200	4520391, 4508693	CMM 49-70-05	49-70-05-300-801-A, REPAIR	ENGINE SERIAL NUMBER IDENTIFICATION ASSEMBLY	C7
Hamilton Sundstrand Poland	APS 2600 E	4953740	CMM 49-33-10	49-33-10-810-801-01, TESTING	Fuel Nozzle Duplex	C7
Hamilton Sundstrand Poland	APS 5000	7000257H02, 7000257H03	CMM 49-92-03	49-92-03-380-801, Repair 03 49-92-03-350-801, Repair 07	Oil Cooler Assembly	C7
Pratt & Whitney Canada, Inc.	PW200 series	3056042-02 3056565-03	CMM 73-11-08	73-11-08-700-801-B00, TESTING 73-11-08-350-002, REPAIR 02	Hybrid fuel nozzle Secondary fuel nozzle	C7



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 - 42 / 43

Place intentionally left blank



Maintenance Capability List

Revision: 143

Date: February 29, 2024

Chapter - Page: 2 - 43 / 43

Place intentionally left blank



Maintenance Capability List

Revision: 150

Date: July 05, 2024

Chapter - Page: 3 - 1 / 3

CHAPTER 3: FAN DRIVE GEAR SYSTEM

Aircraft	Workshop	Make (OEM Mfg)	Model/Type	Part Number	Approved or Accepted Data	ATA Code	EASA Rating
Bombardier CSeries CS100 CS300	Hamilton Sundstrand Poland	Pratt & Whitney	FDGS PW1500G Series	5321771 5318332 5319896	Engine Manual, Cleaning Inspection and Repair Manual, Standard Practice Manual, Special Procedure	72-15-00	C7
Airbus A320neo A319neo A320neo A321neo	Hamilton Sundstrand Poland	International Aero Engines (IAE), LLC	FDGS PW1100G- JM Series	5319663 5319767 5326583	Engine Manual, Cleaning Inspection and Repair Manual, Standard Practice Manual, Special Procedure	72-15-00	C7
Embraer E-JETS	Hamilton Sundstrand Poland	Pratt & Whitney	FDGS PW1900G Series	5319896 5321771	Engine Manual, Cleaning Inspection and Repair Manual, Standard Practice Manual, Special Procedure	72-15-00	C7



Maintenance Capability List

Revision: 151

Date: August 08, 2024

Chapter - Page: 3 - 2 / 3

3.1 FAN DRIVE GEAR SYSTEM COMPONENTS

Make	Model/Type	Part Number	Repair Number	Description	EASA Rating
International Aero Engines (IAE), LLC	FDGS PW1100G-JM Series	5319883-01	SP-72-15 Special Procedures – FDGS PN 5319154 PW1000G-77445-19154-00 E.A.No.: RT19CCF78, RT17CCE26, DDM17CCE26	Carrier Assembly	C7
International Aero Engines (IAE), LLC	FDGS PW1100G-JM Series	5309911-01	SP-72-15 Special Procedures – FDGS PN 5319154 PW1000G-77445-19154-00 E.A. No: EM15CC939, MR15CC939	Inner Support Assembly	C7
International Aero Engines (IAE), LLC	FDGS PW1100G-JM Series	5309914-01	SP-72-15 Special Procedures PW1000G-77445-19154-00 (Inspection)	Gear – Bi Helical Ring	C7
International Aero Engines (IAE), LLC	FDGS PW1100G-JM Series	5309903-01	SP-72-15 Special Procedures PW1000G-77445-19154-00 (Inspection)	Journal Bearing Assembly	C7
International Aero Engines (IAE), LLC	FDGS PW1100G-JM Series	5315079-01	SP-72-15 Special Procedures PW1000G-77445-19154-00 (Inspection)	Manifold Assembly	C7
International Aero Engines (IAE), LLC	FDGS PW1100G-JM Series	5319669-01	SP-72-15 Special Procedures PW1000G-77445-19154-00 (Inspection)	Nozzle-oil	C7
International Aero Engines (IAE), LLC	FDGS PW1100G-JM Series	5309934	SP-72-15 Special Procedures PW1000G-77445-19154-00 (Inspection)	Pin-Support, Inner, Fan Drive Gear System	C7
International Aero Engines (IAE), LLC	FDGS PW1100G-JM Series	5311872	SP-72-15 Special Procedures PW1000G-77445-19154-00 (Inspection)	Scoop-oil	C7



Maintenance Capability List

Revision: 150

Date: July 05, 2024

Chapter - Page: 3 - 3 / 3

Make	Model/Type	Part Number	Repair Number	Description	EASA Rating
International Aero Engines (IAE), LLC	FDGS PW1100G-JM Series	5319664-01	SP-72-15 Special Procedures – FDGS PN 5319154 PW1000G-77445-19154-00 E.A.No.: RT19CCF78, RT17CCE26, DDM17CCE26	Carrier Assembly	C7



Maintenance Capability List

Revision: **157**

Date: **January 20, 2025**

Chapter - **Page: 4 - 1 / 1**

CHAPTER 4: PT6A MAKE AND MODELS

Aircraft	Workshop	Make (OEM Mfg)	Model	Part Number	Description	Approved or Accepted Data	ATA Code	EASA Rating	Capability Rating
For details please check website	Hamilton Sundstrand Poland	Pratt & Whitney Canada	PT6A35	3057768-01	PT6A TURBOPROP GAS TURBINE ENGINE	Overhaul Manual, Maintenance Manual, Illustrated Part Catalogue, Service Bulletins, Component Maintenance Manual, Standard Practice Manual, Information Letters, Service Center Engineering Technical Instructions, Request for Evaluation	72-00-00	B1	Inspection, Repair, Modification, Overhaul
			PT6A114	3104100-01					
			PT6A114A	3044000					
			PT6A135	3029000					
			PT6A135A						
For details please check website	Hamilton Sundstrand Poland	Pratt & Whitney Canada	PT6A41	3018000	PT6A TURBOPROP GAS TURBINE ENGINE	Overhaul Manual, Maintenance Manual, Illustrated Part Catalogue, Service Bulletins, Component Maintenance Manual, Standard Practice Manual, Information Letters, Service Center Engineering Technical Instructions, Request for Evaluation	72-00-00	B1	Inspection, Repair, Modification, Overhaul
			PT6A42	3030700					
			PT6A42A	3120055-01					
			PT6A60A	3102700-01					
			PT6A65B	3101000-01					
PT6A65AG									
For details please check website	Hamilton Sundstrand Poland	Pratt & Whitney Canada	PT6A67B,	3042200,	PT6A TURBOPROP GAS TURBINE ENGINE	Overhaul Manual, Maintenance Manual, Illustrated Part Catalogue, Service Bulletins, Component Maintenance Manual, Standard Practice Manual, Information Letters, Service Center Engineering Technical Instructions, Request for Evaluation	72-00-00	B1	Inspection, Repair, Modification, Overhaul
			PT6A67P,	3072955-01,					
			PT6A67D	3044800					
For details please check website	Hamilton Sundstrand Poland	Pratt & Whitney Canada	PT6A34	3020800	PT6A TURBOPROP GAS TURBINE ENGINE	Overhaul Manual, Maintenance Manual, Illustrated Part Catalogue, Service Bulletins, Component Maintenance Manual, Standard Practice Manual, Information Letters, Service Center Engineering Technical Instructions, Request for Evaluation	72-00-00	B1	Inspection, Repair, Modification, Overhaul